SERVICE BULLETIN

KODAK X-OMAT Processor

Eastman Kodak Company, Health Sciences Division, Imaging Service Center, Rochester, New York 14650

SERVICE BULLETIN NO. 226

October 1995

Kodak AUTOMATIC FILM FEEDER, MODEL RA

DIP SWITCH Location Changed on the ADJUSTMENT CIRCUIT BOARD

To reduce the effect of electrostatic discharge on the FILM FEEDER, the DIP SWITCHES have been relocated on the ADJUSTMENT CIRCUIT BOARD. On current units, the SWITCHES are located on the ADJUSTMENT CIRCUIT BOARD so that they are inside the ELECTRICAL ENCLOSURE. See the illustration. The DIP SWITCHES are not accessible through the FRONT PANEL.

This information is covered in Publication Change Notice No. 2 (Pub No. 5B6743) for the Service Guide (Pub No. 240977) and can be ordered from Advertising and Distribution at 1-800-677-9933. The binder complete Publication Number for the *Kodak* AUTOMATIC FILM FEEDER, MODEL RA is Pub No. 240993.

Note

On FEEDERS with Serial No. 50,899 and above, the DIP SWITCHES are inside the ELECTRICAL ENCLOSURE. See the figures below.



H066_0128ACA
H066_0128AA



H066_0168ACA
H066_0168AA

© Eastman Kodak Company

For more information, please contact:

Eastman Kodak Company
Health Sciences Division
Imaging Service Center
343 State Street, 3rd fl, Bldg 20
Rochester, NY 14650-1131

(800) 336-4722, Press 5

Please be prepared to give your Customer Number and your equipment serial number.

Kodak and *X-Omat* are trademarks.

N-938

101995sb_226.doc

Printed in USA

HEALTH SCIENCES DIVISION

EASTMAN KODAK COMPANY ● ROCHESTER, N.Y. 14650